



CabMaster Premium Library Build 40 Autoupdater Details

New Features

- CMPREM40-I159 All Cabinets: Show Grain Direction on parts in Machining view
- CMPREM40-I153 Report: Quote Reports
- CMPREM40-I152 Report: Quantities reports
- CMPREM40-I151 Report: Poly Reports
- CMPREM40-I150 Report: Hardware Order Reports
- CMPREM40-I149 Report: HardWare List Report
- CMPREM40-I148 Report: Door Report
- CMPREM40-I147 Report: Board List Report
- CMPREM40-I146 Report: Board 3 Column Report
- CMPREM40-I145 Report: Board 2 Column Report
- CMPREM40-I144 Report: Board 1 Column Report
- CMPREM40-I142 CM-Parts: Shelf - Ability to adjust front gap to adjustable holes independently on ends
- CMPREM40-I130 Drawer Cabinets: 'set all' option for drawers
- CMPREM40-I123 Bar Back Cabinets: Added Option export panels with profiles as one part
- CMPREM40-I115 Reports: Default Runner set in use
- CMPREM40-I105 Bench cabinets: Added Remove Back Option
- CMPREM40-I64 Floor DrwDoor: Ability to locally override back hole offset and spacing
- CMPREM40-I57 Fixed Shelves: add quantity to alt settings
- CMPREM40-I54 CM-Design: Add RH-Canopy
- CMPREM40-I38 Reporting: Benchttop Material Name Moved to Components DimName1
- CMPREM40-I37 Reporting: Hardware and Labour Component Description moved to DimName1
- CMPREM40-I19 Drawer cabinets: Set All Drawers Option
- CMPREM40-I18 Material Tags: Offset option
- CMPREM40-I2 Vanity Cabinets: Custom Tables Added To Vanity Panels

Bug Fixes

- CMPREM40-I197 Material Manager: Leaving Spurious Properties in drawings
- CMPREM40-I195 Universal Cabinets: Part text offset from part when using door profile
- CMPREM40-I194 Cabinet Door: Make as Profile Door from the Machining Page causes error
- CMPREM40-I192 Vanity Drawer and Door: Ends without drawer unit not exporting machining
- CMPREM40-I191 Tall Micro Pantry: Lower carcass materials page broken
- CMPREM40-I190 Bench Micro: Panel Bottom could error
- CMPREM40-I188 Bench Angled Micro: Errors on placement

CMPREM40-I187 Bench Micro, Tall Split Return Right and Others: Door and Lower Door Material Pages incorrect

CMPREM40-I184 Universal Cabinets: Construction holes on End Left offset by Bottom/Top piece's front edging selection

CMPREM40-I183 Tall Splay Left and Right: No construction holes for Fixed Shelf

CMPREM40-I182 Floor Micro Drawer: Micro box panel material as Door not working

CMPREM40-I181 Floor Micro Drawer: Materials for Microwave box panels is adjusting lower carcass panel material

CMPREM40-I180 Cabinets with a Micro Frame: errors and incorrect shape when both Panel as Door & Carcass as Panel

CMPREM40-I179 Corner cabinets: Extn back misaligned with rectangular pipe chase

CMPREM40-I178 Universal and CM-Parts Drawers: Cam construction incorrect for Standard and Standard Sink

CMPREM40-I176 DoorMaster LT: Series 3 style 3 & 4: Offset of inner boundary for hog tool was incorrect

CMPREM40-I174 Tall Angled Walk-in Pantries: 'Make as Tall Angled' option behaviour inconsistent

CMPREM40-I173 Tall Angled Walk-in Pantry: 'Make as Tall Angled' optioned causing an error

CMPREM40-I172 Legs: holes not matching position set by Settings

CMPREM40-I171 Wall Filler: Backing piece oversize appears in 3D

CMPREM40-I168 Tall Split Broom: Doors not lining up with carcasses in upper section

CMPREM40-I167 Tall Split Broom: Doors not aligned with Carcass line split

CMPREM40-I166 Tall Cabinets: 'all as 1' door edging not working

CMPREM40-I164 Lift Hinges / Machinable Objects: No option for back holes

CMPREM40-I162 Tall Angled Walk-In Pantry Cabinets: Bottom depth incorrect when ends set to position above bottom

CMPREM40-I161 Drawer sides: Grain direction incorrect in 3D view

CMPREM40-I160 Drawer Sides: Grain direction showing wrong value when material grain direction set to 90 degrees

CMPREM40-I158 Corner Cabinets: Border not cutting when using 2-part construction with T&G

CMPREM40-I157 Vanity drawer Cabinets: Carcass Top Rails Positioned inside Shadow rails

CMPREM40-I141 Universal Cabinets: Shelf construction incorrect when using slanted shelf profiles

CMPREM40-I140 DoorMaster-LT: Shaker and ShakerV missing pricing information in table

CMPREM40-I139 Corner Radius: Reading from door profile settings when profile disabled

CMPREM40-I137 Universal Cabinets: Metal standard drawers placing 2 copies of Runner2Holes

CMPREM40-I136 Corner Shelf: Incorrect "back" point using skewed depth

CMPREM40-I135 Tall Wall Oven: Microwave box ends gaining kick board cut-out

CMPREM40-I134 Bulkhead cabinet: 'all as 1' edging button errors

CMPREM40-I133 Bulkhead Cabinet: Side Bar Errors

CMPREM40-I129 Extrusions: Add Option to Edit Extrusion profiles and Pricing from Pricing/Material and Hardware

CMPREM40-I127 Shadow Rail Extrusions: price in linear metre

CMPREM40-I125 Bulkhead Cabinet: Rails Show Edged Size in 3d

CMPREM40-I124 BulkHead Cabinet: Errors on Placement

CMPREM40-I122 Bar Back Corner: Panel as Door Option Erroring

CMPREM40-I121 End Panels and Bar Backs: Errors in Cabinet Properties

CMPREM40-I120 Wall RH: Continuous shelf holes not lining up on duct chase

CMPREM40-I118 Tall Wall Oven Drawer: Bottom hinge plate does not follow manual override.

CMPREM40-I117 Universal Cabinets: Premilling - Oversize still occurring on pieces with 0mm edging.

CMPREM40-I114 Floor Angled Display: Recess shelf doesn't move the adj shelf holes

CMPREM40-I110 Floor Corner Cabinet: Benchtop Seal is always on for sides and backs

CMPREM40-I108 Drawers: Drawerbank with Shadow Rails not showing Rail in 3D with a Drawer Front off

CMPREM40-I107 Drawer Cabinets: When Shadow Rails used and Bottom drawer front Off then fronts misplaced

CMPREM40-I106 Bench Split Cabinets: Errors on placement

CMPREM40-I104 Tall Return Cabinets: Mullion shelf holes

CMPREM40-I103 Tall Split Cabinets: Shaker Door settings not controlling right door

CMPREM40-I101 Wall Ovens: Panel Material as Door is not working

CMPREM40-I100 Wall RH: Pipe chase sides machining on wrong face

CMPREM40-I99 Wine Rack Cabinets: Shelves and Divisions not showing in 3D

CMPREM40-I98 DoorMaster LT: Series 3 style 2 to 5 and Series 5 Style (various) : Offset of 2nd Profile Tool Incorrect

CMPREM40-I92 Universal Cabinets: All listening to Tall Shelf Adj settings

CMPREM40-I90 Furn Floor Drawer Split: View machining list missing extra drawer parts

CMPREM40-I89 Furn Floor Drawer Split: Parts missing from output.

CMPREM40-I87 Floor Cabinet Back Rails: Tongue on wrong side when using T&G with Cam Override

CMPREM40-I84 Return cabinets: T&G for carcass front disappearing when Back machined face set to 'Inside'

CMPREM40-I83 Wine, Angled and Splay cabinets: Shelves listening to bottom tongue setting for rebates

CMPREM40-I82 Floor Seryery Left and Right: Recursive formulas MachJoinYFaceL and MachJoinYFaceR

CMPREM40-I81 Seryery cabinets: Grooves for rails on opposite side

CMPREM40-I79 Doormaster Lt: Series 5 Style 8 Door Image incorrect

CMPREM40-I77 End Panels: Controlling Depth with Properties Sidebar when Flush with doors is switched on.

CMPREM40-I73 Reports: Door Edge Components Missing Material Name In DimName1

CMPREM40-I72 Corner cabinets: hinge cup holes missing in 3d view when door quantity set to 1x2

CMPREM40-I70 Parts1 Shelf: Component Top Edge Size incorrect

CMPREM40-I67 Doormaster LT: Series 5 Style 8 not machining second profile layer

CMPREM40-I66 Floor Multi: error concerning MachHingeAutoMove

CMPREM40-I63 Floor DrwDoor: Drawer Separator Division Not Drilling Construction Holes Correctly

CMPREM40-I61 Polyshape: exporting machining erroring

CMPREM40-I58 Fixed Shelves: Single back hole not being placed in centre of part

CMPREM40-I56 Tall Corner: Mid Fixed Shelf not applying adj. gap when changed to Adjustable

CMPREM40-I53 Bar Backs: Machining View list errors

CMPREM40-I52 Floor and Wall Universal: Horizontal Division Incorrect Thickness for Snapping

CMPREM40-I51 Drawer fronts: Drawer Front Not Showing Shakers in Elevation

CMPREM40-I50 Corner Cabinets: Shelves not visible when using P2p Cut-offs

CMPREM40-I49 Floor DrwDoor: Erroring when changing from bank

CMPREM40-I48 Finger Pull Handles: Unable To Be Turned On Or Off

CMPREM40-I46 Tall End Panels: Shaker mid rail not lining up when extended to floor

CMPREM40-I45 DoorMaster LT: Profiles with veins do not have any machining in universal doors

CMPREM40-I44 Universal Cabinets: Shelf holes incorrectly positioned when centred to shelf

CMPREM40-I43 Universals: drawer Fronts have no ability to remove handles

CMPREM40-I42 End panels and Fillers: Import errors when turning on door profile

CMPREM40-I41 Elevation View: Door Swings Intermittently Not Showing In Elevation View

CMPREM40-I40 Floor Micro Drawer: Missing the Appliance image in Elevation

CMPREM40-I39 Shadow rails: Cut-outs not showing as full depth when using press outs

CMPREM40-I34 Angled Cabinets: Front Kickboard Erroring

CMPREM40-I31 CM-Parts shelves: Errors on placement

CMPREM40-I30 Tall Angled Plus: Legs Using Incorrect Layers

CMPREM40-I29 Tall Broom: Continuous Adjustable Shelf Holes Still Present When Using Fixed Shelves

CMPREM40-I28 Kickboard Cabinets: Ends disappearing when using cut-outs

CMPREM40-I27 Universal Cabinets: Door applying top gap when using shadow rails

CMPREM40-I26 CM-Parts Shelf: Oversize in Depth Showing In Non Machining Views

CMPREM40-I23 Tall (and Split) Broom: shaker mid rail too high with full doors

CMPREM40-I21 Wall Wine Display: Cannot remove bottom

CMPREM40-I17 Wall Return Cabinets: Shelf Holes Missing in Mullion

CMPREM40-I16 Shadow Rail Grain: Grain Direction Override Unavailable When Using Carcass Material by Type

CMPREM40-I15 Shelf Standard: Oversize is showing up in all views

CMPREM40-I14 Universal Cabinets: Angled Door Back Checkboxes Behaving Incorrectly

CMPREM40-I13 Tall Beverage: Parts Showing incorrectly

CMPREM40-I12 Tall Wall Oven: Lower handles Incorrectly Controlled by Upper handles' checkboxes

CMPREM40-I11 Tall Wall Ovens: Hinge plates in upper doors not moving with hinge cup

CMPREM40-I10 Tall and Floor Cabinets: Shaker Door Not Aligning with Cabinets When Bottom Removed

CMPREM40-I9 Continuous shelf holes: issues when extending ends back

CMPREM40-I8 Wall RH: Duct Pipe Chase cut-out too big in Bottom piece.